




[Click Here To View
Item at
www.GapPower.com](http://www.GapPower.com)

*Sales • Rentals
Parts & Service*

Bull Dog Power Products®
 13435 Industrial Park Blvd.
 Minneapolis, MN 55441
 1-877-992-7637 Fax 1-877-927-6370



**Ballast Box Set
 P40033A**



*Two Clamps Included

⌚ P40050 1/4-20 x 5/8 Screw

⊙ P33440 Washer

P100509 Ballast Lid

P100508 Ballast Box

P33491 Strain Relief

P40053 1/4-20 Nut

P46005C Switch Cover

P46009 Fuse Holder

P100310 Switch Cover Plate

P46056 1/4" Washer

P46025 1/2" Electrical Nut

P33472 3" x 3/16" Sheet Rubber


P46007 Connector Ring Terminal

P33235 Connector 1/4" Female

P33248 Connector

P46058 1/4-20 x 1" Hex Head Cap Screw

P33470 Bushing



P12000W

7 P100831 1 kW
 Light Fixture
 Complete

8 P100817 1kW Bulb

9 P100883
 - Lens
 - Cable

10 Reflector (P100831)
 P101767

11 Lampholder (P100831)
 P101758

**Lamp Socket
 P101765**

12 Ballast
 P46010

13 P46005 Switch



14 P46006 Fuse

15 P46003 14' Cord

16 P101377 8' Cord
 with 30 Amp Plug




1




P12000W

2



3 P100482 Base



4



Snap Pin
P101157

5

P46052
3/8 Knob

6



P40003
Wheel

Not Pictured Under Ballast Box

